

Norman H. Bangerter
Governor
Kenneth L. Alkema
Executive Director
Don A. Ostler, P.E.
Director

State of Utah

TAL QUALITY

COPY

DEPARTMENT OF ENVIRONMENTAL QUALITY DIVISION OF WATER QUALITY

288 North 1460 West P.O. Box 144870 Salt Lake City, Utah 84114-4870 (801) 538-6146 (801) 538-6016 Fax



May 4, 1992

DIVISION OF OIL GAS & MINING

Mr. Paul Spor, Manager North Lily Mining Company P. O. Box 421 Eureka, Utah 84628

RE:

Compliance and Monitoring Report,

UGW230001

Dear Mr. Spor:

This letter is to acknowledge the quarterly monitoring report received by this office April 13, 1992.

We note that a 35 gpd leak occurred in the pad system February 4 1992, but subsided shortly thereafter to .1 - .5 gpd. Conditions of the construction permit incorporated into the discharge permit requires reduction in application rates if the leak exceeds 50 gpd. However we recommend the continuing small leak be investigated and eliminated to reduce the potential for ground water pollution. Continued long term presence of fluid in leak detection media creates an increased risk for release. This issue also becomes critical when closure of the facility is undertaken. There is a need to document contamination, and remediation is required, especially under CERCLA programs.

If you have any questions call Mack Croft at 538-6146.

Sincerely,

Larry J. Mize, P.E., Manager

Ground Water Protection Section

LJM:mlj

cc:

Roger Foisey - District Engineer

Central Utah District Health Department

Division of Oil, Gas and Mining

Q:NORTHLILLET
FILE:NORTH LILY MINING